

PRODUCT CHANGE NOTIFICATION

Product Category FIBER DISTRIBUTION 20221024-2

Product Group CONNECTIVITY & PATHWAYS

ISSUE DATE: 24-Oct-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Some Fiber Distribution products will be discontinued. Please review the product notification for a list of the affected parts.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	10	31
Old product discontinuation date*	2023	1	22

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerService@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com	
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA APPR. MURILLO	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

FORM C2-1003 DATE: 06 APR 21 APPR: MURILLO

IMPACTED PART NUMBER(s)	Replacement Part 1
--------------------------------	---------------------------

NKF6BN011-NM01	NO-REPLACEMENT
NKF6BN011-NM02	NO-REPLACEMENT
NKF6BN011-NM03	NO-REPLACEMENT
NKF6BN012-NM01	NO-REPLACEMENT
NKF6BN012-NM02	NO-REPLACEMENT
NKF6BN012-NM03	NO-REPLACEMENT
NKF6BN013-NM01	NO-REPLACEMENT
NKF6BN013-NM02	NO-REPLACEMENT
NKF6BN013-NM03	NO-REPLACEMENT
NKF6EL02L-LM01	NO-REPLACEMENT
NKF6EL02L-LM02	NO-REPLACEMENT
NKF6EL02L-LM03	NO-REPLACEMENT
NKF6EL02L-LM05	NO-REPLACEMENT
NKF6EL02L-LM10	NO-REPLACEMENT
NKF6EL02S-LM01	NO-REPLACEMENT
NKF6EL02S-LM02	NO-REPLACEMENT
NKF6EL02S-LM03	NO-REPLACEMENT
NKF6EL02S-LM05	NO-REPLACEMENT
NKF6EL02S-LM10	NO-REPLACEMENT
NKF6ER02L-LM01	NO-REPLACEMENT
NKF6ER02L-LM02	NO-REPLACEMENT
NKF6ER02L-LM03	NO-REPLACEMENT
NKF6ER02L-LM05	NO-REPLACEMENT
NKF6ER02S-LM01	NO-REPLACEMENT
NKF6ER02S-LM02	NO-REPLACEMENT
NKF6ER02S-LM05	NO-REPLACEMENT
NKF6ER02S-LM10	NO-REPLACEMENT
NKF6FL022-FM02	NO-REPLACEMENT
NKF6FL022-FM05	NO-REPLACEMENT
NKF6FL022-FM10	NO-REPLACEMENT
NKF6FL02F-FM02	NO-REPLACEMENT
NKF6FL02F-FM03	NO-REPLACEMENT
NKF6FL02F-FM10	NO-REPLACEMENT
NKF6FL02L-FM01	NO-REPLACEMENT
NKF6FL02L-FM03	NO-REPLACEMENT
NKF6FL02L-FM05	NO-REPLACEMENT
NKF6FL02S-FM01	NO-REPLACEMENT
NKF6FL02S-FM02	NO-REPLACEMENT
NKF6FL02S-FM05	NO-REPLACEMENT
NKF6FL02S-FM10	NO-REPLACEMENT
NKF6FR022-FM02	NO-REPLACEMENT
NKF6FR022-FM03	NO-REPLACEMENT
NKF6FR022-FM10	NO-REPLACEMENT
NKF6FR02F-FM01	NO-REPLACEMENT
NKF6FR02F-FM03	NO-REPLACEMENT

NKF6FR02F-FM05	NO-REPLACEMENT
NKF6FR02L-FM01	NO-REPLACEMENT
NKF6FR02L-FM02	NO-REPLACEMENT
NKF6FR02L-FM05	NO-REPLACEMENT
NKF6FR02L-FM10	NO-REPLACEMENT
NKF6FR02S-FM02	NO-REPLACEMENT
NKF6FR02S-FM03	NO-REPLACEMENT
NKF6FR02S-FM10	NO-REPLACEMENT
NKF6GL022-2M01	NO-REPLACEMENT
NKF6GL022-2M03	NO-REPLACEMENT
NKF6GL022-2M05	NO-REPLACEMENT
NKF6GL022-SM01	NO-REPLACEMENT
NKF6GL022-SM02	NO-REPLACEMENT
NKF6GL022-SM05	NO-REPLACEMENT
NKF6GL022-SM10	NO-REPLACEMENT
NKF6GL02S-SM02	NO-REPLACEMENT
NKF6GL02S-SM03	NO-REPLACEMENT
NKF6GL02S-SM10	NO-REPLACEMENT
NKF6GR022-2M01	NO-REPLACEMENT
NKF6GR022-2M02	NO-REPLACEMENT
NKF6GR022-2M03	NO-REPLACEMENT
NKF6GR022-2M05	NO-REPLACEMENT
NKF6GR022-2M10	NO-REPLACEMENT
NKF6GR022-SM01	NO-REPLACEMENT
NKF6GR022-SM02	NO-REPLACEMENT
NKF6GR022-SM05	NO-REPLACEMENT
NKF6GR022-SM10	NO-REPLACEMENT
NKF6GR02S-SM02	NO-REPLACEMENT
NKF6GR02S-SM03	NO-REPLACEMENT
NKF6GR02S-SM10	NO-REPLACEMENT
NKFD1W6EIDSCZ	NO-REPLACEMENT
NKFP61BN1NNM001	NO-REPLACEMENT
NKFP61BN3NNM001	NO-REPLACEMENT
NKFP623L22SM001	NO-REPLACEMENT
NKFP623L22SM003	NO-REPLACEMENT
NKFP623L22SM004	NO-REPLACEMENT
NKFP623L22SM010	NO-REPLACEMENT
NKFP623L22SM015	NO-REPLACEMENT
NKFP623LSSSM001	NO-REPLACEMENT
NKFP623LSSSM002	NO-REPLACEMENT
NKFP623LSSSM004	NO-REPLACEMENT
NKFP623LSSSM005	NO-REPLACEMENT
NKFP623LSSSM015	NO-REPLACEMENT
NKFP623LSSSM020	NO-REPLACEMENT
NKFP623R22SM002	NO-REPLACEMENT
NKFP623R22SM003	NO-REPLACEMENT
NKFP623R22SM005	NO-REPLACEMENT
NKFP623R22SM010	NO-REPLACEMENT

NKFP623R22SM020	NO-REPLACEMENT
NKFP623R2LSM018	NO-REPLACEMENT
NKFP623RSSSM002	NO-REPLACEMENT
NKFP623RSSSM003	NO-REPLACEMENT
NKFP623RSSSM005	NO-REPLACEMENT
NKFP623RSSSM010	NO-REPLACEMENT
NKFP623RSSSM020	NO-REPLACEMENT
NKFP62ELLLSM001	NO-REPLACEMENT
NKFP62ELLLSM003	NO-REPLACEMENT
NKFP62ELLLSM004	NO-REPLACEMENT
NKFP62ELLLSM010	NO-REPLACEMENT
NKFP62ELLLSM015	NO-REPLACEMENT
NKFP62ELLSSM001	NO-REPLACEMENT
NKFP62ELLSSM002	NO-REPLACEMENT
NKFP62ELLSSM004	NO-REPLACEMENT
NKFP62ELLSSM005	NO-REPLACEMENT
NKFP62ELLSSM015	NO-REPLACEMENT
NKFP62ELLSSM020	NO-REPLACEMENT
NKFP62ERLLSM001	NO-REPLACEMENT
NKFP62ERLLSM002	NO-REPLACEMENT
NKFP62ERLLSM003	NO-REPLACEMENT
NKFP62ERLLSM004	NO-REPLACEMENT
NKFP62ERLLSM005	NO-REPLACEMENT
NKFP62ERLLSM007	NO-REPLACEMENT
NKFP62ERLLSM010	NO-REPLACEMENT
NKFP62ERLLSM015	NO-REPLACEMENT
NKFP62ERLLSM018	NO-REPLACEMENT
NKFP62ERLLSM020	NO-REPLACEMENT
NKFP62ERLLSM030	NO-REPLACEMENT
NKFP62ERLSSM001	NO-REPLACEMENT
NKFP62ERLSSM002	NO-REPLACEMENT
NKFP62ERLSSM003	NO-REPLACEMENT
NKFP62ERLSSM004	NO-REPLACEMENT
NKFP62ERLSSM005	NO-REPLACEMENT
NKFP62ERLSSM010	NO-REPLACEMENT
NKFP62ERLSSM015	NO-REPLACEMENT
NKFP62ERLSSM018	NO-REPLACEMENT
NKFP62ERLSSM020	NO-REPLACEMENT
NKFP62ERLSSM030	NO-REPLACEMENT
NKF6ERO2L-LM10	NO-REPLACEMENT
NKF6ERO2S-LM03	NO-REPLACEMENT
NKF6FL022-FM01	NO-REPLACEMENT
NKF6FL022-FM03	NO-REPLACEMENT
NKF6FL02F-FM01	NO-REPLACEMENT
NKF6FL02F-FM05	NO-REPLACEMENT
NKF6FL02L-FM02	NO-REPLACEMENT
NKF6FL02L-FM10	NO-REPLACEMENT
NKF6FL02S-FM03	NO-REPLACEMENT

NKF6FR022-FM01	NO-REPLACEMENT
NKF6FR022-FM05	NO-REPLACEMENT
NKF6FR02F-FM02	NO-REPLACEMENT
NKF6FR02F-FM10	NO-REPLACEMENT
NKF6FR02L-FM03	NO-REPLACEMENT
NKF6FR02S-FM01	NO-REPLACEMENT
NKF6FR02S-FM05	NO-REPLACEMENT
NKF6GL022-2M02	NO-REPLACEMENT
NKF6GL022-2M10	NO-REPLACEMENT
NKF6GL022-SM03	NO-REPLACEMENT
NKF6GL02S-SM01	NO-REPLACEMENT
NKF6GL02S-SM05	NO-REPLACEMENT
NKF6GR022-SM03	NO-REPLACEMENT
NKF6GR02S-SM01	NO-REPLACEMENT
NKF6GR02S-SM05	NO-REPLACEMENT
NKFD1W6EIDSC	NO-REPLACEMENT
NKFP61BN2NNM001	NO-REPLACEMENT
NKFP623L22SM002	NO-REPLACEMENT
NKFP623L22SM005	NO-REPLACEMENT
NKFP623L22SM020	NO-REPLACEMENT
NKFP623LSSSM003	NO-REPLACEMENT
NKFP623LSSSM010	NO-REPLACEMENT
NKFP623R22SM001	NO-REPLACEMENT
NKFP623R22SM004	NO-REPLACEMENT
NKFP623R22SM015	NO-REPLACEMENT
NKFP623RSSSM001	NO-REPLACEMENT
NKFP623RSSSM004	NO-REPLACEMENT
NKFP623RSSSM015	NO-REPLACEMENT
NKFP62ELLISM002	NO-REPLACEMENT
NKFP62ELLISM005	NO-REPLACEMENT
NKFP62ELLISM020	NO-REPLACEMENT
NKFP62ELLISM003	NO-REPLACEMENT
NKFP62ELLISM010	NO-REPLACEMENT
NKF5BN012-NM01	NO-REPLACEMENT
NKF5BN012-NM02	NO-REPLACEMENT
NKF5BN012-NM03	NO-REPLACEMENT
NKF5FL022-FM01	NO-REPLACEMENT
NKF5FL022-FM02	NO-REPLACEMENT
NKF5FL022-FM03	NO-REPLACEMENT
NKF5FL022-FM05	NO-REPLACEMENT
NKF5FR022-FM01	NO-REPLACEMENT
NKF5FR022-FM02	NO-REPLACEMENT
NKF5FR022-FM05	NO-REPLACEMENT
NKF5FR022-FM10	NO-REPLACEMENT
NKF6BN012-NM02	NO-REPLACEMENT
NKF6BN012-NM03	NO-REPLACEMENT
NKF6FL022-FM02	NO-REPLACEMENT
NKF6FL022-FM03	NO-REPLACEMENT

NKF6FL022-FM10	NO-REPLACEMENT
NKF6FR022-FM01	NO-REPLACEMENT
NKF6FR022-FM03	NO-REPLACEMENT
NKF6FR022-FM05	NO-REPLACEMENT
NKF9BN012-NM01	NO-REPLACEMENT
NKF9BN012-NM02	NO-REPLACEMENT
NKFP51BN2NNM001	NO-REPLACEMENT
NKFP523L22SM002	NO-REPLACEMENT
NKFP523L22SM003	NO-REPLACEMENT
NKFP523L22SM005	NO-REPLACEMENT
NKFP523L22SM010	NO-REPLACEMENT
NKFP523L22SM020	NO-REPLACEMENT
NKFP523R22SM001	NO-REPLACEMENT
NKFP523R22SM003	NO-REPLACEMENT
NKFP523R22SM004	NO-REPLACEMENT
NKFP523R22SM010	NO-REPLACEMENT
NKFP523R22SM015	NO-REPLACEMENT
NKFP61BN2NNM001	NO-REPLACEMENT
NKFP623L22SM001	NO-REPLACEMENT
NKFP623L22SM003	NO-REPLACEMENT
NKFP623L22SM004	NO-REPLACEMENT
NKFP623L22SM010	NO-REPLACEMENT
NKFP623L22SM015	NO-REPLACEMENT
NKFP623R22SM001	NO-REPLACEMENT
NKFP623R22SM002	NO-REPLACEMENT
NKFP623R22SM004	NO-REPLACEMENT
NKFP623R22SM005	NO-REPLACEMENT
NKFP623R22SM015	NO-REPLACEMENT
NKFP623R22SM020	NO-REPLACEMENT
NKFP91BN2NNM001	NO-REPLACEMENT
NKFP923L22SM001	NO-REPLACEMENT
NKFP923L22SM003	NO-REPLACEMENT
NKFP923L22SM004	NO-REPLACEMENT
NKFP923L22SM005	NO-REPLACEMENT
NKFP923L22SM010	NO-REPLACEMENT
NKFP923L22SM015	NO-REPLACEMENT
NKFP923L22SM020	NO-REPLACEMENT
NKFP923R22SM001	NO-REPLACEMENT
NKFP923R22SM002	NO-REPLACEMENT
NKFP923R22SM003	NO-REPLACEMENT
NKFP923R22SM004	NO-REPLACEMENT
NKFP923R22SM005	NO-REPLACEMENT
NKFP923R22SM010	NO-REPLACEMENT
NKFP923R22SM015	NO-REPLACEMENT
NKFP923R22SM020	NO-REPLACEMENT
NKFPX1BN2NNM001	NO-REPLACEMENT
NKFPX23L22SM001	NO-REPLACEMENT
NKFPX23L22SM003	NO-REPLACEMENT

NKFPX23L22SM004	NO-REPLACEMENT
NKFPX23L22SM010	NO-REPLACEMENT
NKFPX23L22SM015	NO-REPLACEMENT
NKFPX23R22SM001	NO-REPLACEMENT
NKFPX23R22SM002	NO-REPLACEMENT
NKFPX23R22SM004	NO-REPLACEMENT
NKFPX23R22SM005	NO-REPLACEMENT
NKFPX23R22SM015	NO-REPLACEMENT
NKFPX23R22SM020	NO-REPLACEMENT
NKFSTMARD	NO-REPLACEMENT
NKFSTMPC5BL	NO-REPLACEMENT
NKFSTMPC6EI	NO-REPLACEMENT
NKFSTMPC6EI-C	NO-REPLACEMENT
NKFXBN012-NM01	NO-REPLACEMENT
NKFXBN012-NM03	NO-REPLACEMENT
NKFXFL022-FM1	NO-REPLACEMENT
NKFXFL022-FM2	NO-REPLACEMENT
NKFXFL022-FM3	NO-REPLACEMENT
NKFXFR022-FM01	NO-REPLACEMENT
NKFXFR022-FM02	NO-REPLACEMENT
NKFXFR022-FM05	NO-REPLACEMENT
NKFXFR022-FM10	NO-REPLACEMENT
NKSTMEI	NO-REPLACEMENT
NKSTMIG	NO-REPLACEMENT
NKSTMWH	NO-REPLACEMENT
NKSTMYL/N	NO-REPLACEMENT
RNKSTEI	NO-REPLACEMENT
RNKSTIG	NO-REPLACEMENT
RNKSTMBL	NO-REPLACEMENT
RNKSTMEI	NO-REPLACEMENT
RNKSTMIW	NO-REPLACEMENT
RNKSTMYL	NO-REPLACEMENT
RNKSTWH	NO-REPLACEMENT
NKF5FL022-FM10	NO-REPLACEMENT
NKF5FR022-FM03	NO-REPLACEMENT
NKF6BN012-NM01	NO-REPLACEMENT
NKF6FL022-FM01	NO-REPLACEMENT
NKF6FL022-FM05	NO-REPLACEMENT
NKF6FR022-FM02	NO-REPLACEMENT
NKF6FR022-FM10	NO-REPLACEMENT
NKF9BN012-NM03	NO-REPLACEMENT
NKFP523L22SM001	NO-REPLACEMENT
NKFP523L22SM004	NO-REPLACEMENT
NKFP523L22SM015	NO-REPLACEMENT
NKFP523R22SM002	NO-REPLACEMENT
NKFP523R22SM005	NO-REPLACEMENT
NKFP523R22SM020	NO-REPLACEMENT
NKFP623L22SM002	NO-REPLACEMENT

NKFP623L22SM005	NO-REPLACEMENT
NKFP623L22SM020	NO-REPLACEMENT
NKFP623R22SM003	NO-REPLACEMENT
NKFP623R22SM010	NO-REPLACEMENT
NKFP623R2LSM018	NO-REPLACEMENT
NKFP923L22SM002	NO-REPLACEMENT
NKFP923R2LSM018	NO-REPLACEMENT
NKFPX23L22SM002	NO-REPLACEMENT
NKFPX23L22SM005	NO-REPLACEMENT
NKFPX23L22SM020	NO-REPLACEMENT
NKFPX23R22SM003	NO-REPLACEMENT
NKFPX23R22SM010	NO-REPLACEMENT
NKFSTMABL	NO-REPLACEMENT
NKFSTMPC5BL-C	NO-REPLACEMENT
NKFSTSABU	NO-REPLACEMENT
NKFXBN012-NM02	NO-REPLACEMENT
NKFXFL022-FM10	NO-REPLACEMENT
NKFXFL022-FM5	NO-REPLACEMENT
NKFXFR022-FM03	NO-REPLACEMENT
NKSTMBL	NO-REPLACEMENT
NKSTMIW	NO-REPLACEMENT
RNKSTBL	NO-REPLACEMENT
RNKSTIW	NO-REPLACEMENT
RNKSTMIG	NO-REPLACEMENT
RNKSTMWH	NO-REPLACEMENT
RNKSTYL	NO-REPLACEMENT
NKFD1W12AQDLC	FD1W12AQDLCZ
NKFD1W12AQDLC-R	FD1W12AQDLCZ
NKFD1W12AQDLCZ	FD1W12AQDLCZ
NKFD1W12AQDSC	FD1W12AQDSCZ
NKFD1W12AQDSCZ	FD1W12AQDSCZ
NKFD1W12BLDLC	NO-REPLACEMENT
NKFD1W12BLDLCZ	NO-REPLACEMENT
NKFD1W12BLDSC	FD1W12AQDSCZ
NKFD1W12BLDSCZ	FD1W12AQDSCZ
NKFD1W12BUDLCZ	FD1W12BUDLCZ
NKFD1W12BUDLCZN	FD1W12BUDLCZ
NKFD1W12BUDLCZ-R	FD1W12BUDLCZ
NKFD1W12BUDSCZ	FD1W12BUDSCZ
NKFD1W12EIDLC	FD1W12EIDLCZ
NKFD1W12EIDLCZ	FD1W12EIDLCZ
NKFD1W12EIDSC	FD1W12EIDSCZ
NKFD1W12EIDSCZ	FD1W12EIDSCZ
NKFD1W24AQDLC	FD1W24AQDLCZ
NKFD1W24AQDLC-R	FD1W24AQDLCZ
NKFD1W24AQDLCZ	FD1W24AQDLCZ
NKFD1W24BLDLC	NO-REPLACEMENT
NKFD1W24BLDLCZ	NO-REPLACEMENT

NKFD1W24BUDLCZ	FD1W24BUDLCZ
NKFD1W24BUDLCZN	FD1W24BUDLCZ
NKFD1W24EIDLC	FD1W24EIDLCZ
NKFD1W24EIDLCZ	FD1W24EIDLCZ
NKFD1W6AQDLCZ/N	NO-REPLACEMENT
NKFD1W6AQDSC	FD1W6AQDSCZ
NKFD1W6AQDSCZ	FD1W6AQDSCZ
NKFD1W6BLDSC	FD1W6AQDSCZ
NKFD1W6BLDSCZ	FD1W6AQDSCZ
NKFD1W6BUDLCZ/N	NO-REPLACEMENT
NKFD1W6BUDSCZ	FD1W6BUDSCZ
NKFD1W6EIDSC	FD1W6EIDSCZ
NKFD1W6EIDSCZ	FD1W6EIDSCZ