



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000796

DATE: 17-Feb-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX20091ATM/V+T	N/A			Part reactivated from prior notice: M000793
Lead-Free Conversion	DS1818R-10/T&R	DS1818R-10+T&R	21-Aug-2015	17-Feb-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS9108-8#	N/A	21-Aug-2015	17-Feb-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX14691ETP+	MAX14691ATP+	21-Aug-2015	17-Feb-2017	The part was not released
Discontinuance	MAX14692ETP+	MAX14692ATP+	21-Aug-2015	17-Feb-2017	The part was not released
Discontinuance	MAX1531EVKIT	N/A	21-Aug-2015	17-Feb-2017	EVKIT is No Longer Supported
Discontinuance	MAX2553ETN+	N/A	21-Aug-2015	17-Feb-2017	The part was not released
Discontinuance	MAX2553ETN+T	N/A	21-Aug-2015	17-Feb-2017	The part was not released
Change to Prior Notice	MAX1304ECM/V+	MAX1304ECM+	21-Aug-2015	17-Feb-2017	The part was not released
Change to Prior Notice	MAX1304ECM/V+T	MAX1304ECM+T	21-Aug-2015	17-Feb-2017	The part was not released
Change to Prior Notice	MAX7302ATE+	N/A	21-Aug-2015	17-Feb-2017	Part can no longer be manufactured
Change to Prior Notice	MAX9951DCCB+D	N/A	21-Aug-2015	17-Feb-2017	Part can no longer be manufactured
Change to Prior Notice	MAX9951DCCB+TD	N/A	21-Aug-2015	17-Feb-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Mar-2015