

16245 Vineyard Blvd, Morgan Hill, CA 95037 Tel. (408) 919-0200 Fax. (408) 919-0201 www.linengineering.com

February 7, 2022

## Product Obsolescence Notification

Dear Valued Customers:

This letter serves as a formal notification of the manufacture obsolescence and End-of-Life (EoL) of the stepper driver products listed below:

- R701-RO
- R710-RO
- Including any customizations or variations of the above products.

The R701-RO and R710-RO drivers have been a valued product for Lin Engineering for many years. An integrated chip (IC) that is necessary for the built-in firmware has been discontinued by our supplier, and we have exhausted all possibilities and been unsuccessful in securing a compatible replacement to continue offering the product as-is.

The direct replacement of R701-RO driver is the R701P-RO. This driver meets or exceeds all operational requirements of the R701-RO while following the same form factor.

The R710-RO driver does not have a direct replacement at this time, but we offer a suitable replacement in the R725-RO which meets or exceeds the operational requirements of the R710-RO driver. The form factor and mating connector is different, but pin-out functions are compatible and serve the same function with little modification. The R725-RO can also be used as a suitable replacement for the R701-RO driver.

We apologize for any inconvenience and are committed to satisfy your future requirements.

Sales Support Email: <u>sales@linengineering.com</u>

Technical Support Email: <u>techsupport@linengineering.com</u>