

# TE Connectivity

Product Change Notification: P-16-012761

### PCN Date: 21-MAR-16

# TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

#### General Product Description:

New SAP order number for Relay V23074-A1001-A403 out of EMEA production in Evora

#### Description of Changes

The SAP order number for Relay V23074-A1001-A403 will change from 8-1393292-4 to 4-1904124-3 out of EMEA production in Evora.

Reason for Changes:					
Part status change.Optimization of TE internal Processes require respective change of TE order number.					
Estimated Dates:					
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):				
	01-JUN-2016				
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):				
	No Mixed Shipments				

#### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
8-1393292-4	NO			"V23074A1001A403"			

#### Part Number(s) being Modified:

	Part umber	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
8-13	93292-4	NO			"V23074A1001A403"			

### Part Number(s) being Modified:

	Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
8	3-1393292-4	NO			"V23074A1001A403"			