



Product Obsolescence Notification

PCN # 10547522

With Replacement

To: All active customers
From: Cathy Maly - Product Manager Mini-Fit

Date: May 5, 2012

Series / Product Family: 43879

Part Numbers Affected: See Attached Parts List

Replacement Parts: See Attached Parts List

Product Description: Mini-Fit® CPI Headers

Reason for Obsolescence Parts contain tin lead, being replaced by lead free parts

Product Image:



Last Order Entry Date: 5-Nov-12

Obsolescence Effective Date 5-Nov-12

For further information please contact your local sales representative.

Molex, Inc.

2222 Wellington Court

Lisle, IL 60532

TEL: 630-969-4747

www.molex.com

Part Number	Replacement
438790033	Select Gold & Tin Lea 438790055 Select Gold and tin (lead free)
438790034	Select Gold & Tin Lea 438790056 Select Gold and tin (lead free)
438790036	Select Gold & Tin Lea 438790058 Select Gold and tin (lead free)
438790038	Select Gold & Tin Lea 438790060 Select Gold and tin (lead free)
438790040	Select Gold & Tin Lea 438790062 Select Gold and tin (lead free)
438790043	Select Gold & Tin Lea 438790065 Select Gold and tin (lead free)
438796007	Select Gold & Tin Lea 438796015 Select Gold and tin (lead free)
438796011	Select Gold & Tin Lea 438796016 Select Gold and tin (lead free)
438796018	Select Gold & Tin Lea 438796042 Select Gold and tin (lead free)
438796021	Select Gold & Tin Lea 438796044 Select Gold and tin (lead free)
438797001	Select Gold & Tin Lea 438796045 Select Gold and tin (lead free)
438799901	Overall Tin Lead 438790055 Overall tin (lead free)
438799904	Duplicate Part Numbe 438790058
438790045	Duplicate Part Numbe 438790023