

PRODUCT CHANGE NOTIFICATION

PCN#: INDUSTRIALNET COPPER **20191113-1**

ISSUE DATE: _____ 20191113

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

RJ45 Field Terminable Plug is being discontinued.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*			

***Important:** A return material authorization (RMA) may be obtained for the affected part numbers listed above if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have

IMPACTED PART NUMBER(s) ISPS688FA	REPLACEMENT PART NUMBER(s) FP6X88MTG
---	--