

PRODUCT CHANGE NOTIFICATION

Product Category FIBER CONNECTORS 20220725-2

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 25-Jul-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

The increasing trend towards fusion-splice and OptiCam connectors means the field-polish solution is being simplified. The FIELDKIT termination kit and FIELDKITRFB replenishment kits will continue to be sold to support FLCSSBUY, FLCSEMBLY, and FSCM5BL field-polish connectors. All other field polish connectors & consumables are being discontinued. Customers are encouraged to become familiar with these fusion-splice and/or OptiCam connectors & select the option that best supports project needs.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	7	25
Old product discontinuation date*	2022	10	23

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

Product Groups

CABLE COPPER, FIBER CABLE AND CONNECTORS

CONVERGED INFRASTRUCTURE

COPPER & NETKEY COPPER, FIBER, CABLE

DATA CENTER SOFTWARE

DC CONNECTIVITY

DUCT AND ABRASION

ID, SAFETY AND ACCESSORIES

IMS SMARTZONE HARDWARE

INDUSTRIALNET COPPER

INDUSTRIALNET FIBER

INDUSTRIALNET OUTLETS

IOT SOFTWARE

IOT SOLUTIONS

MISC

OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT

POWER CONNECTORS, GROUNDING AND STEEL

PRE-CONFIGURED IA

TIES AND TERMINALS

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2 (For Complex only)	Grouping	Discontinuation
					Date
FLCDM900BLY	Compatible	FLCS2/9SOCPXAQ	FLCSMCXAQY		23-Oct-22
FSCSBU	Compatible	FSCS2/9SOCU9BU	FSC2SCBU		23-Oct-22
FLCDM3.0BL	Compatible	FLCS2/9SOCPXAQ	FLCSMCXAQY		23-Oct-22
FLCDM900EI	Compatible	FLCSMC6EIY			23-Oct-22
FLCDM900EIY	Compatible	FLCSMC6EIY			23-Oct-22
FLCDMBLY	Compatible	FLCS2/9SOCPXAQ	FLCSMCXAQY		23-Oct-22
FLCDMEIY	Compatible	FLCSMC6EIY			23-Oct-22
FLCDS3.0BU	Compatible	FLCS2/9SOCU9BU	FLCSSCBUY		23-Oct-22
FLCDS900BUY	Compatible	FLCS2/9SOCU9BU	FLCSSCBUY		23-Oct-22
FLCDSBUY	Compatible	FLCS2/9SOCU9BU	FLCSSCBUY		23-Oct-22
FLCSM3.0BL	Compatible	FLCS2/9SOCPXAQ	FLCSMCXAQY		23-Oct-22
FLCSM3.0EI	Compatible	FLCSMC6EIY			23-Oct-22
FLCSMEIY	Compatible	FLCSMC6EIY			23-Oct-22
FLCSS3.0BU	Compatible	FLCS2/9SOCU9BU	FLCSSCBUY		23-Oct-22
FSCDM	Compatible	FSC2MC6EI			23-Oct-22
FSCM2.05BL	Compatible	FSCS2/9SOCPXAQ	FSC2MCXAQ		23-Oct-22
FSCM2.0BL	Compatible	FSCS2/9SOCPXAQ	FSC2MCXAQ		23-Oct-22
FSCMBL	Compatible	FSCS2/9SOCPXAQ	FSC2MCXAQ		23-Oct-22
FSCS2.0BU	Compatible	FSCS2/9SOCU9BU	FSC2SCBU		23-Oct-22
FSTMABL	Compatible	FST2MCXAQ			23-Oct-22
FSTMARD	Compatible	FST2MC6EI			23-Oct-22
FSTSABU	Compatible	FST2SCBU			23-Oct-22
FSCMRD	Compatible	FSC2MC6EI			23-Oct-22
FSCDM5BL	Compatible	FSCS2/9SOCPXAQ	FSC2MCXAQ		23-Oct-22
FIELDKIT-G	Compatible	FIELDKIT			23-Oct-22
FIELDKITUPG	Compatible	FOCTT2-KIT			23-Oct-22
FSYR-X	Compatible	FIELDKITRFB			23-Oct-22
FJPMR	Compatible	FIELDKITRFB			23-Oct-22
FJPXY	Compatible	FIELDKITRFB			23-Oct-22
FPP5-L	Compatible	FIELDKITRFB			23-Oct-22
FPF1-V	Compatible	FIELDKITRFB			23-Oct-22
FLCFPLF-X	Compatible	FIELDKITRFB			23-Oct-22
FWP-C	Compatible	FIELDKITRFB			23-Oct-22
FALC	No Replacement	NO-REPLACEMENT			23-Oct-22
FSCDVR	No Replacement	NO-REPLACEMENT			23-Oct-22
FGLS	No Replacement	NO-REPLACEMENT			23-Oct-22
FTWZR	No Replacement	NO-REPLACEMENT			23-Oct-22
FWBTL	No Replacement	NO-REPLACEMENT			23-Oct-22
FWRKMAT	No Replacement	NO-REPLACEMENT			23-Oct-22
FSCRIBE	No Replacement	NO-REPLACEMENT			23-Oct-22
FKS	No Replacement	NO-REPLACEMENT			23-Oct-22
FSCOPEY	No Replacement	NO-REPLACEMENT			23-Oct-22
FLOUPEX10	No Replacement	NO-REPLACEMENT			23-Oct-22
FCRP5	No Replacement	NO-REPLACEMENT			23-Oct-22
FJPKGU	No Replacement	NO-REPLACEMENT			23-Oct-22
FPAD	No Replacement	NO-REPLACEMENT			23-Oct-22
FLCPAD	No Replacement	NO-REPLACEMENT			23-Oct-22
FHSCT-W	No Replacement	NO-REPLACEMENT			23-Oct-22