

PRODUCT CHANGE NOTIFICATION

Product Category COPPER - CABLE - 1G 20200610-01

Product Group COPPER CABLE

ISSUE DATE: 20200610

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Parts are being discontinued in order to streamline the product offering

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2020	6	10
Old product discontinuation date*	2020	9	10

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Type	Replacement Part 1
PUC5504BLY	Direct Replacement	PUC5504BL-EY
PUC5504BUY	Direct Replacement	PUC5504BU-EY
PUC5504IGY	Direct Replacement	PUC5504IG-EY
PUC5504GRY	Direct Replacement	PUC5504GR-EY
PUC5504RDY	Direct Replacement	PUC5504RD-EY
PUC5504ORY	Direct Replacement	PUC5504OR-EY
PUC5504VLY	Direct Replacement	PUC5504VL-EY
PUC5504WHY	Direct Replacement	PUC5504WH-EY
PUC5504YLY	Direct Replacement	PUC5504YL-EY