

TE Connectivity

Product Change Notification: E-19-007161 PCN Date: 13-MAY-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
HEAVY DUTY BURNER CLIP ST

Description of Changes

The following part numbers are being obsoleted (obsolete status). the replacement part is 1969755-1 which is very similar with this part. Please verify that replacement part are suitable for your specific application- Drawings are available via TE.com.

Reason for Changes: Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter. Estimated Dates: Last Order Date (Obsolete Parts Only): 68-AUG-2019 Last Ship Date (Obsolete Parts Only): Last Date for Mixed Shipments: (Changed Parts Only): 99-AUG-2019 No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>640751-1</u>	YES				1969755-1		-
<u>640751-1</u>	YES				1969755-1		

Part Number(s) being Modified:

Part	Part Discontinued per PCN	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number		Drawing	Number	Number(s)	Number	Number(s)	Difference
640751-1	YES				1969755-1	•	

Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
640751-1	YES	Diawing	Number		1969755-1	Number(s)	Difference