



Product Change Notification (PCN)

PCN Number Date Issued

Reason for Change

Change Type Description

Reason for Short Notice

Assessment of Change

Internal Molex Qualification Date

Sample Availability Date (Changed Part)

Planned Implementation Date

RELEASED

Before Change

After Change

BEFORE

- Molex part numbers 1111451101, 1111451201, 1111451301, 1111455001, 1111459401, 2058963252, 747529611, 1111456002, 1111456003 & 1111456004 in Molex Philippines with below SPQ:

PN	Current SAP SPQ
1111451101	50
1111451201	35
1111451301	35
1111455001	15
1111459401	30
2058963252	35
747529611	30
1111456002	30
1111456003	30
1111456004	15

AFTER

- This letter is to inform you of Molex part numbers 1111451101, 1111451201, 1111451301, 1111455001, 1111459401, 2058963252, 747529611, 1111456002, 1111456003 & 1111456004 will be changed to below SPQ:

PN	Corrected SPQ from RPK Drawing
1111451101	35
1111451201	35
1111451301	30
1111455001	15
1111459401	40
2058963252	35
747529611	30
1111456002	24
1111456003	24
1111456004	15

- Product Impact

This is not a process, material or supplier change – This is just change in delivery unit. No impact to fit, form or function.



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:509643**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Updated Quantity Template

Molex Part Number	Current Standard Pack Quantity (DU)	Current Minimum Order Quantity	New Standard Pack Quantity (DU)	New Minimum Order Quantity
1111451101	50	N/A	30	N/A
1111451201	50	N/A	35	N/A
1111451301	38	N/A	30	N/A
1111455001	15	N/A	18	N/A
1111459401	30	N/A	40	N/A
2058963252	50	N/A	35	N/A
747529611	20	N/A	30	N/A
1111456002	30	N/A	24	N/A
1111456003	30	N/A	24	N/A
1111456004	15	N/A	18	N/A