## **Product Change Notification**

molex	Product Change Notification			
Date Issued :	July 12, 2022	PCN Number :	512351	
Reason for Change :	Obsolete			
Description of Change :	Molex production control team wanted immediate obsolescence as below part can not be produced further due to the below Short Notice Justification: Raw material is not available, the material is pre- plated and we can no longer obtain it, the replacement will be post plated.			
Reason for Short Notice :	Supplier Constraints			
Planned Implementation Date :	August 04, 2022			
Recommended replacement parts :	Please see the attached replacement parts list .xls file.			
Last Time Buy Date for Obsolete Parts :	July 18, 2022			
Last Time Ship Date for Obsolete Parts	: July 25, 2022			

**Before Picture** 

1 1

### KK Terminal



Molex Confidential Information © 2016 Molex – All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.

## molex

"After the last time ship date, Molex will no longer manufacture the products included within this notification and all related tooling will be decommissioned. For assets that are customer owned, the owner has 90 days after the last time ship date to claim the tooling."

You may address inquires regarding this PCN by clicking on the below link <u>mailto:pcn\_coordinator@molex.com?subject=PCN\_Notification:512351</u> or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : PCN Notification: 512351 " in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com

# molex

Page: 2 of 2

# RELEASED

### Overview

After Picture

- Parts are going Obsolete as the pre-plated raw material is no longer available, replacement part number will be 39000376, it will post plated
- Product Impact
  - No impact to fit, form or function
- Part Number Impact
  - 39000374 and 39000375
- PPAP and samples available upon request

2 @ 2016 Molex – All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.

 PCN No
 Part List

 512351
 0039000374