



June 30, 2017

Change Notification for 157-00097 to 157-00287

To Our Valued Customer:

To better serve your business, we inform you of the following change.

HellermannTyton part number 157-00097 is no longer available. It is replaced by HellermannTyton part number 157-00287. The difference in these two items is:

"Design change to increase tensile strength  
Packaging change from 500 pcs/bag and 2500 pcs/carton to bulk with 4000 pcs/carton"

Our records show that your part number is 157-00097. We ask that future purchase orders be placed for the new HellermannTyton part number. Any open orders will be revised to the new part number.

Due to the urgency of this change, we ask that you acknowledge this notification within 10 business days. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative.

We appreciate your support in this change and thank you for your continued business.

Sincerely,

Kelsey Shrader  
Quality Project Engineer