

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of the immediate availability of new software release for XPort Pro.

Change Type

Software

Products Affected

XPort Pro (Evolution)

Part Number	Description	Old Revision	New Revision
XPP1002000-02R	XPort Pro Device Networking Module, Evolution OS, AES Encryption, 16MB SRAM, Extended Temperature, RoHS, Bulk	E15	F15
XPP100200S-02R	XPort Pro Device Networking Module, Evolution OS, AES Encryption, 16MB SRAM, Extended Temperature, RoHS, Sample	E16	F16
XPPDK1000-EVO-02	XPort Pro Evolution Development Kit with 16 MB RAM, RoHS	D14	E14

Description and Extent of Change

Lantronix is pleased to announce the release of new and improved XPort Pro Evolution OS firmware version 5.5.0.2R5. It provides security protocol enhancement along with a bug fix.

Key highlights of this release are:

- Enhancement to TLS 1.2 protocol- Elliptic curve with SHA-2 HASH
- DHCP Bug fix after ARP timeout

Effect of Change on Fit, Form, Function, Quality, or Reliability

Product Variant	Part Number	Software Version
XPort Pro (Evolution)	XPP1002000-02R XPP100200S-02R XPPDK1000-EVO-02	Firmware Version: 5.5.0.2R5

The updated SDK release is available for download via Lantronix forums (<http://forums.lantronix.com>).

Effective Date of Change

Affected products will begin shipping with the new software from the factory starting 1st February 2019.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.