

# Change Notice

# LB, UB & UB2 Series

## Changes to UB & UB2 Pushbuttons; LB, UB & UB2 Illuminated Pushbuttons; LB, UB & UB2 Indicators

Type of Change:

- Engineering
- Part Number
- Product
- Appearance

I. The location of production will change for UB and UB2 Pushbuttons, LB, UB and UB2 Illuminated Pushbuttons, and LB, UB and UB2 Indicators from the China factory to the Philippines factory. The box in which the switches are packaged for shipping will read "PHILIPPINES FACTORY" instead of "CHINA FACTORY." The lot number on the side of the switch cases will have a dot mark above the second digit instead of the first digit. All of these modifications will apply to all UL/CSA approved standard and custom products.



Changes for LB, UB & UB2 Pushbuttons & Indicators

Example: UB215SK	Lot Number	Shipping Box
<b>Before Changes</b>	<p>Lot Number Above First Digit</p> <p>Enlarged to show detail</p>	<p>"CHINA FACTORY" printed on side of box</p>
<b>After Changes</b>	<p>Lot Number Above Second Digit</p> <p>Enlarged to show detail</p>	<p>"PHILIPPINES FACTORY" printed on side of box</p>

The following groups of products reflect the changes of production location, lot number marks and packaging, and include all UL approved standard and custom products:

- UB Nonilluminated Pushbuttons
- UB Illuminated Pushbuttons
- LB Indicators
- UB2 Nonilluminated Pushbuttons
- UB2 Illuminated Pushbuttons
- UB Indicators
- LB Illuminated Pushbuttons
- UB2 Indicators

**Notes**

There are no changes to the switches' dimensions or specifications.  
 The location of the Lot Number may vary depending on the part number.  
 See website or contact the factory if more details are needed.

**Effective Date**

Changes to LB, UB and UB2 Pushbuttons, Illuminated Pushbuttons and Indicators will be effective October 2016.



<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

# Change Notice



# LB, UB & UB2 Series

## Changes to UB & UB2 Pushbuttons; LB, UB & UB2 Illuminated Pushbuttons; LB, UB & UB2 Indicators

Type of Change:

- Engineering     Part Number
- Product         Appearance

2. UB and UB2 Nonilluminated Pushbuttons, and LB, UB and UB2 Illuminated Pushbuttons, all with UL approval, will have a change on the switch case for all standard and custom devices. Previously, the UL symbol appeared on the case with factory code 078. After the change, the code 080 will appear next to the UL symbol. The table below illustrates the modification.

UL Factory Code Change on Switch Case	
Before Change	After Change
	



This group of products will have revisions to the UL factory code. They include all UL approved standard and custom products.

- UB Nonilluminated Pushbuttons
- LB Illuminated Pushbuttons
- UB Illuminated Pushbuttons
- UB2 Nonilluminated Pushbuttons
- UB2 Illuminated Pushbuttons

Type of Change:

- Engineering     Part Number
- Product         Appearance

3. UB and UB2 Nonilluminated Pushbuttons, and LB, UB and UB2 Illuminated Pushbuttons, and LB, UB, and UB2 Indicators with UL approval, will transition from the older logo to the updated one as shown below.

Logo Change on Switch Case	
Before Change	After Change
	

Several models from LB, UB and UB2 Series will display the new logo. This change will apply to all UL approved standard and custom products from the following groups:

- UB Nonilluminated Pushbuttons
- UB2 Nonilluminated Pushbuttons
- LB Illuminated Pushbuttons, snap-in mount (does not include panel seal)
- UB Illuminated Pushbuttons (does not include super bright bicolor LED)
- UB2 Illuminated Pushbuttons (does not include super bright Blue/Amber bicolor LED)
- LB Indicators
- UB Indicators (does not include super bright bicolor LED)
- UB2 Indicators (does not include super bright Blue/Amber bicolor LED)

**Notes**

For factory code or logo changes, there will be no revisions to the switches' dimensions or specifications. The location of the factory code or logo may vary depending on the part number. See website or contact the factory if more details are needed.

**Effective Date**

Changes to LB, UB and UB2 Pushbuttons, Illuminated Pushbuttons and Indicators will be effective October 2016.



<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435