

Global Change Notification (GCN)

Product Family MX064 FEMALE 10630493

GCN Number

Series 31402,31403,31404,34975,34977 March 21, 2014


Date Issued


Reason For Change

Change In Packaging Specifications

Change Description

The purpose of this letter is to inform you that to improve the packing quality and improve the Volumetric Penalty, change of packing method will be implemented on Series# 31402,31403,31404,34975,34977 connectors. We will only change the packing method and not change the SPQ. Please refer to attached file for implement date, method of identification and customer part





Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Not Applicable	
Assessment Of Change (How Product Will Be Qualified & Validated)	Drop test	
Internal Molex Qualification Date (Planned Date Information Available)	February 21, 2014	
Sample Availability Date (Changed Part)	February 28, 2014	
Date of Implementation	September 21, 2014	
Method of Identifying Change	The height of carton is change from 212mm to 165mm	
Recommended Replacement Parts		
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com