

#### 1 Products affected

SBU PG PUG Type Connectors   02 007 002 0000002380 See list below Connectors	Product hierarchy no. *			chy no. *	Part no.	SBU	Product Type	Customer part no.
02 007 002 0000002380 See list below Connectors 6080	SBU	PG	PUG	Туре				
02 007 002 0000002300 See list below Conflectors 0000	02	007	002	0000002380	See list below	Connectors	6080	


<sup>\*</sup>SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers af	fected for type 6080			
3-137-731	3-137-752	3-137-753	3-137-754	

### 2 Type of change

- Change of packaging
- · Change of packaging quantity

## 3 Detailed description of change



# 4 Reason of change

- Economical use of material
- Packaging quantities are optimized for better serving of all desired quantities.

### 5 Release date

The change takes effect in ww 08/2023 (Date code 2308 or higher on label). Parts on stock will be used upon depletion.

Product Change Notification						PCN 6080-Package Change		
owner	creation date	release date	released by	change order	rev	page	D40 070 200	
lutzjo	21.12.2022	21.12.2022	muehlema	2024942	В	1 of 2	D10-070-300	





6	Impa	act of change and	recommended action
		Form	
		Fit	
		Function	
		Manufacturing	
		Label	
	$\boxtimes$	Packaging	No action required; box size unchanged.

## 7 Reference Documents

Kind of document	Document Title
Data Sheet	Data Sheet 6080

Product Change Notification						PCN 6080-Package Change		
owner	creation date	release date	released by	change order	rev	page	D40 070 200	
lutzjo	21.12.2022	21.12.2022	muehlema	2024942	В	2 of 2	D10-070-300	