

Tallysman Wireless Inc.

Ottawa, Ontario, Canada Monday, March 22, 2021

Product Obsolescence Notification

Dear Customers:

This letter serves as formal notification that Tallysman Wireless Incorporated (Tallysman) is discontinuing the production of the products listed below.

Discontinued Products:

- 33-VSP6137-zz • 33-VSP6037-zz
 - 33-VSP6337-zz 33-VSP6137L-zz
- 33-VSP6537-zz • 33-VSP6237-zz
- 33-VSP6537L-zz • 33-VSP6237L-zz

As a part of our continuous commitment to provide customers with the most current technology and best experience, Tallysman is discontinuing manufacturing selected products from our standard product offerings due to outdated technology.

Tallysman has served the industrial market for over 12 years and we understand the importance of the industrial market life cycle. However, in today's rapidly changing world, components become obsolete for many reasons, including continual advances in technologies. We will make our best effort to provide a product with the same functionality and quality.

Recommended Alternative Product Lines:

- 33-VSP6037L-xx VSP6037L VeroStar[™] Full GNSS Precision Antenna +L-band
- 33-VSP6337L-xx VSP6337L VeroStar™ Triple-band GNSS Precision Antenna +L-band

Warranty and After Market Parts Support for Obsoleted Products:

Warranty: Standard Tallysman warranty terms are applicable for any last time buy products.

After Market Parts Support: Tallysman will support aftermarket parts for 3 years from the date of this notification. We will maintain components to service repairable items to support our customers' installations.

We apologize for any inconvenience this announcement may cause and remain eager to meet your future requirements.

Should you have any question about this notification, please do not hesitate to contact us.

Carlos Valenzuela	Chris Russell	Allen Crawford
Director Quality Assurance	Director Distributor Sales	Vicepresident of Product Development
carlos.valenzuela@tallysman.com	chris.russell@tallysman.com	allen.crawford@tallysman.com
Tel: +1 (613) 591-3131 Ext. 131	Tel: +1 (613) 591-3131 Ext. 135	Tel: +1 (613) 591-3131 Ext. 101

Tallysman Wireless Incorporated | 36 Steacie Drive | Ottawa, Ontario, Canada | K2K 2A9 | www.tallysman.com | Tel: +1 613 591 3131