## **Product/Process Change Notifications**



PCN - 14 106

						Release	e Date: Dece	mber	16	2014
Product Name:	AirMax VSE									
	Product									
Product Manager:	Talee Luo									
Subject:	Notification of Change with Immediate Effectivity									
Distribution:	General									
Type of Change:	Design Change									
Change Description:	Change the Circular Undercut to Rectangular Undercut at interference locator.  RECTANGULAR UNDERCUT  UNDERCUT  AFTER DESIGN CHANGE WITH RECTANGULAR UNDERCUT  RECTANGULAR UNDERCUT  AFTER DESIGN CHANGE WITH RECTANGULAR UNDERCUT									
Reason for Change:	To improve the short filling at interference Locator & avoid Poor finishing									
Affected Parts:	10044366-101LF,10044366-102LF,10044366-103LF,10044366-104LF,10044366-105LF,10044366-108LF									
Effective Date of Change:	January 5, 2015									
Last Time Buy Date:	NA									
Last Disty Return Date:	NA									
Last Time Shipment Date	NA									
Datasheet Attached?	NA									
Qual/Test Data Attached?	NA									
Samples Availability Date:	December	16	2014							
Available Alternatives?	NA									
Questions?	Contact your local FCI Representative, or Product Manager									
	Talee LUO - Product Manager									
	luota @fci.com +86 769 88669299									

## Note

Customer shall intimate the product Manager any Concern regarding the PCN within 3 weeks of the release date. PCN is considered approved by the customer if no communication is received within 3 weeks