

## MICRON\_7300 Firmware 95420260 Maintenance Release

PCN: 34147

Published: 2021-04-21

Туре:	Firmware Revision		
Description:	Micron is releasing 7300 maintenance firmware 95420260 replacing the initial 95420100 production release firmware. The 95420260 firmware is associated with non-Security Enabled Drives (non-SED) part numbers only and provides the following updates:		
	-Feature & performance enhancements		
	-LED status and activity upgrades		
	-System stability improvements		
	-General error and protocol improvements		
	-Asynchronous power-loss improvements		
Anticipated Impact:	95420260 firmware does not affect basic form, fit, function of the 7300 drives.		
Reason:	Better Align With Industry Standard, In	nproved Product Quality and Reliability	
Product Affected:	All part numbers which are non-securi	ty enabled drives (non-SED) part numbers	
Affected Micron Part Number	Recommended Replace	ment Customer Part Number	
Component			
MTFDHBA400TDG-1AW1ZABY	Y	557-MTFDHBA400TDG-1AW1ZABYY-ND	
MTFDHBA400TDG-1AW4ZABY		557-MTFDHBA400TDG-1AW4ZABYY-ND	
MTFDHBA400TDG-2AW1ZABYY			
MTFDHBA480TDF-1AW1ZABYY		557-MTFDHBA480TDF-1AW1ZABYY-ND	
MTFDHBA480TDF-1AW4ZABYY	<i>(</i>	557-MTFDHBA480TDF-1AW4ZABYY-ND	
MTFDHBA480TDF-2AW1ZABYY			
MTFDHBA800TDG-1AW1ZABY		557-MTFDHBA800TDG-1AW1ZABYY-ND	
MTFDHBA800TDG-1AW4ZABY	Y	557-MTFDHBA800TDG-1AW4ZABYY-ND	
MTFDHBA800TDG-2AW1ZABYY			
MTFDHBA960TDF-1AW1ZABYY	ζ	557-MTFDHBA960TDF-1AW1ZABYY-ND	
MTFDHBA960TDF-1AW4ZABYY	<i>(</i>	557-MTFDHBA960TDF-1AW4ZABYY-ND	
MTFDHBA960TDF-2AW1ZABYY			
MTFDHBE1T6TDG-1AW1ZABY	Y	557-MTFDHBE1T6TDG-1AW1ZABYY-ND	
MTFDHBE1T6TDG-1AW4ZABY	Y	557-MTFDHBE1T6TDG-1AW4ZABYY-ND	
MTFDHBE1T9TDF-1AW1BABYY			
MTFDHBE1T9TDF-1AW1ZABYY	<i>č</i>	557-MTFDHBE1T9TDF-1AW1ZABYY-ND	
MTFDHBE1T9TDF-1AW4ZABYY	Z .	557-MTFDHBE1T9TDF-1AW4ZABYY-ND	
MTFDHBE3T2TDG-1AW1ZABY	Y	557-MTFDHBE3T2TDG-1AW1ZABYY-ND	
MTFDHBE3T2TDG-1AW4ZABY	Y	557-MTFDHBE3T2TDG-1AW4ZABYY-ND	
MTFDHBE3T8TDF-1AW1BABYY			
MTFDHBE3T8TDF-1AW1ZABYY	č	557-MTFDHBE3T8TDF-1AW1ZABYY-ND	
MTFDHBE3T8TDF-1AW4ZABYY	<del>č</del>	557-MTFDHBE3T8TDF-1AW4ZABYY-ND	
MTFDHBE6T4TDG-1AW1ZABY	Y	557-MTFDHBE6T4TDG-1AW1ZABYY-ND	
MTFDHBE6T4TDG-1AW4ZABY	Y	557-MTFDHBE6T4TDG-1AW4ZABYY-NI	
MTFDHBE7T6TDF-1AW1BABYY			

MTFDHBE7T6TDF-1AW4ZABYY	557-MTFDHBE7T6TDF-1AW4ZABYY-ND
MTFDHBE800TDG-1AW1ZABYY	557-MTFDHBE800TDG-1AW1ZABYY-ND
MTFDHBE800TDG-1AW4ZABYY	557-MTFDHBE800TDG-1AW4ZABYY-ND
MTFDHBE960TDF-1AW1BABYY	
MTFDHBE960TDF-1AW1ZABYY	557-MTFDHBE960TDF-1AW1ZABYY-ND
MTFDHBE960TDF-1AW4ZABYY	557-MTFDHBE960TDF-1AW4ZABYY-ND
MTFDHBG1T9TDF-1AW1ZABYY	557-MTFDHBG1T9TDF-1AW1ZABYY-ND
MTFDHBG1T9TDF-1AW4ZABYY	557-MTFDHBG1T9TDF-1AW4ZABYY-ND
MTFDHBG1T9TDF-2AW1ZABYY	
MTFDHBG3T8TDF-1AW1ZABYY	557-MTFDHBG3T8TDF-1AW1ZABYY-ND
MTFDHBG3T8TDF-1AW4ZABYY	557-MTFDHBG3T8TDF-1AW4ZABYY-ND
MTFDHBG3T8TDF-2AW1ZABYY	

\*Materials that have been ordered are in **bold**.

Method of Identification:	FW version printed on the label (see attached label image).	
Micron Sites Affected:	All Sites  MSB - Singapore	
Sample Available:	2021-04-21	
Product Ship Date:	2021-05-21	

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

 ${\bf Micron\ Confidential\ and\ Proprietary\ Information}$ 

## **Attachments**