

PRODUCT CHANGE NOTIFICATION

PCN#: COPPER CABLE

20191023-1

ISSUE DATE:

20191023

IMPACTED REGIONS:

NA

EMEA

LATAM

AP

REASON FOR CHANGE:

DISCONTINUATION

OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

The Cat 6 28AWG series of cables are being discontinued with no replacement at this time.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2019	5	13

***Important:** A return material authorization (RMA) may be obtained for the affected part numbers listed above if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
PUP6C2804BL-U	NO REPLACEMENT
PUP6C2804BU-U	NO REPLACEMENT
PUP6C2804IG-U	NO REPLACEMENT
PUP6C2804GR-U	NO REPLACEMENT
PUP6C2804RD-U	NO REPLACEMENT
PUP6C2804OR-U	NO REPLACEMENT
PUP6C2804VL-U	NO REPLACEMENT
PUP6C2804WH-U	NO REPLACEMENT
PUP6C2804YL-U	NO REPLACEMENT
PUR6C2804BL-U	NO REPLACEMENT
PUR6C2804BU-U	NO REPLACEMENT
PUR6C2804IG-U	NO REPLACEMENT
PUR6C2804GR-U	NO REPLACEMENT
PUR6C2804RD-U	NO REPLACEMENT
PUR6C2804OR-U	NO REPLACEMENT
PUR6C2804VL-U	NO REPLACEMENT
PUR6C2804WH-U	NO REPLACEMENT
PUR6C2804YL-U	NO REPLACEMENT