

April 2016

## 3M<sup>™</sup> Thermally Conductive Interface Pad 5592S Discontinuation Notice

To Our Valued Customers:

We regret to inform you that **3M<sup>™</sup> Thermally Conductive Interface Pad 5592S** will be discontinued. This discontinuation is effective June 1, 2016 and we are offering a last buy opportunity until the effective date.

You are receiving this letter because your company has purchased the above mentioned product during the last two (2) years. Please circulate this notice to the people in your organization who need to know of this change so they can follow up as necessary with either 3M or your customers.

3M recommends **3M<sup>™</sup> Thermally Conductive Interface Pads 5595S** as a possible alternative solution. Keep in mind that the recommended alternative series does not have the same specifications as the one being discontinued, so testing should be conducted to ensure it will meet your application needs.

If you have any questions or require samples for testing, please contact your local 3M representative.

Thank you for your understanding and continued partnership with 3M.

Sincerely,

**JH Jeen** Global Business Manager 3M Electronics Materials Solutions Division