

Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #:	N-12-45	Last Buy Deadline for Submission of Order:	19-Dec-2013				
Issue Date:	19-Dec-2012	Last Eligible Ship Date:	19-Mar-2014				
Contact: E-mail:	IDT Clock Marketing Team clocks@idt.com						
PRODUCT(S) AFFECTED: (List Replacement Part #(s), if any)		ATTACHMENT ■ Yes	□ No				
Selective Clock devices as listed in Attachment I will be discontinued.							
DEASON FO	OP DISCONTINUANCE.						
		Freescale Fab MOS6 closs	ire				
-	ASON FOR DISCONTINUANCE: Replace slower speed with faster speed offerings Other: Dissolete Fab Technology / Process Dissolete Assembly Technology / Process Dissolete Package / Material Declined Market STOMER NOTIFICATION: a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you ough this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before exerting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information. st time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance IDT at its sole discretion unless otherwise agreed by IDT in writing.						
☐ Obsolete Fab Technology / Process ☐ Obsolete Assembly Technology / Process							
☐ Declined N	Market		_				
As a result of through this l	f discontinuance reason(s) listed above, II Product Discontinuance Notice (PDN). W	e recommend you to check detailed specifications	s before				
by IDT at its	s sole discretion unless otherwise agreed b						
Customer:		E-Mail Address:					
Name/Date:		Phone#:					
Title:		Fax# :					
CUSTOMER	R COMMENTS:						
IDT ACKNO	OWLEDGEMENT:						
Received By:		Date:					



Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: N-12-45

Affected Part Numbers

Discontinued Part#	Discontinued Part#	Discontinued Part#	Discontinued Part#
MC68160AEB	MC68160AFB	MC68160BAE	MC68160BFB
MC68160AEBR2	MC68160AFBR2	MC68160BAER2	MC68160BFBR2