

Infoletter Number: 211902			Date: 11.05.2021
Title: SHT85 supply and product number definition			
Product Identification: Sensirion part number SHT85, Two order codes: 3.000.074/ 3.000.458			
Change Severity:	☐ Major		
Reason for Change:	☐ Design	☐ Production	□ Logistics
	☐ Manufacturing Location	Quality/Reliability	☐ Material
Change Description: In February 2021, a new version of the SHT85 was introduced with conformal coating (3.000.458).			
Due to global supply chain challenges, this product is not available until further notice, being replaced by the identical non-coated previous version of the SHT85 (3.000.074). All orders with part number 3.000.074 and 3.000.458 will be fulfilled with 3.000.074. Sensirion will re inform as soon as the 100% transition to SHT85 (3.000.458) is fully manageable again.			
Identification Method to Distinguish Change: Please connect the available SHT85 version order code (3.000.074) to your system, as latest price list is not reflecting this number anymore! MPN: SHT85, Order number: 3.000.074 (available version) MPN: SHT85, Order number: 3.000.458 (new version, coming later)			
Qualification Data:	☐ available	will be available by	□ not applicable
Samples:	available	will be available by	□ not applicable
Quantifiable Impact on Quality & Reliability: - none			
Estimated Implementation Date*: 2021			
Last Time Buy Date: N/A.			
Last Ship Date: N/A			
* The Estimated Implementation Date is the forecasted date that a customer may expect to receive changed product. This may be affected by fluctuations in supply and demand.			
Sensirion Contact: info@sensirion.com and/or Key-Account Manager			

All correspondence must be sent to the Sensirion contact e-mail address listed above.