



NO: NT-068
DATE: June 2012

PRODUCT: NT631C Backlight Tubes
TYPE: Partial Discontinuation

Replacement Backlights for Discontinued NT631C Operator Interface Terminals will be Discontinued March 2013

Effective March 30, 2013, Omron Automation and Safety will discontinue the replacement backlight tubes for specific NT631C Operator Interface Terminal models that were discontinued 7 years ago.

Affected Parts

Discontinued Backlight Model	Operator Interface Terminal Models Discontinued in 2006	Recommended Backlight Replacement	Recommended Operator Interface Terminal Replacement
NT631C-CFL01	NT631C-ST151-EV2 NT631C-ST151B-EV2	No replacement	NT631C-ST153-EV3 NT631C-ST153B-EV3 NS10-TV00-V2 NS10-TV00B-V2
NT631C-CFL02	NT631-ST141-V2 NT631-ST141B-V2 NT631-ST141-EV2 NT631-ST141B-EV2	No replacement	NT631C-ST153-V3 NT631C-ST153B-V3 NT631C-ST153-EV3 NT631C-ST153B-EV3

Note: The screen data and ladder program from discontinued NT631-ST141□-EV2 is compatible with NT631C-ST153□-□V3.