



TE Connectivity

Product Change Notification: P-15-012125 PCN Date: 08-0CT-15

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Reduction of the gaps

Description of Changes

To minimize the gaps the internal radii of the base- and cover-corners are modified, small changes of the geometry of the ribs inside the cover are done, plastic material on the base is added and at the coil body of the Micro A Relay an chamfer is added. All modifications are done inside the relay. The relay drawings remain unchanged. The protection against pollution is improved. No change of relay parameters.

Reason for Changes:		
Product improvement.		
Estimated Dates:		
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):	
	01-JAN-2016	
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):	
	31-DEC-2016	

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1414687-0	NO						
6-1393292-3	NO			"V23074A2002A403"			
8-1393292-4	NO			"V23074A1001A403"			

Part Number(s) being Modified:

		Customer	Customer Part	Alias Part Number(s)	Substitute Part		
Number	per PCN	Drawing	Number	` '	Number	Part Number(s)	Difference
1-1414687-0	NO						
6-1393292-3	NO			"V23074A2002A403"			
8-1393292-4	NO			"V23074A1001A403"			

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Alias Fait Nulliber(5	Number	Part Number(s)	Difference
6-1393292-3	NO			"V23074A2002A403"			
8-1393292-4	NO			"V23074A1001A403"			