

TE Connectivity

Product Change Notification: P-22-022620

PCN Date: 06-MAY-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:	
2POS,PIN DIA 8.0,PIN HSG,ASSY	

Description of Changes

Dear Customer, we hereby inform you about a tool replacement of a mold tool for TE component part "RADIAL SEAL 56.4 X 50" for "2POS,PIN DIA 8.0,PIN HSG,ASSY". Tool build and serial production at the supplier.

Reason for Changes:

Product improvement.As a result of our continuous strive for quality improvements of our production, we hereby inform you upfront about a new tool 21-1959955, which is under construction In order to meet all specification requirements to replace the current one, which is worn out. Estimated Dates: Last Order Date (Obsolete Parts Only): Last Ship Date (Obsolete Parts Only): Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-2141227-1	NO						
2-2141227-1	NO						
<u>2141227-2</u>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>1-</u> 2141227-1	NO						
<u>2-</u> 2141227-1	NO						
2141227-2	NO						