

# PRODUCT CHANGE NOTIFICATION

Product Category COMPUTER PRINTABLES 20211115-1

Product Group ID AND SAFETY

ISSUE DATE: 15-Nov-21

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Some laser/ink jet labels will be discontinued with replacement parts

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2021	11	24
Old product discontinuation date*	2022	2	13

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2
C100X075YJJ	Compatible	C100X050YJJ	
C400X400YJJ	Compatible	C400X200YJJ	
C138X019FJJ	Complex	C138X019FJC	LS8EQ
N025X075FJJ	Compatible	N050X075FJJ	N025X150FJJ
N100X075FJJ	Compatible	N050X075FJJ	N100X150FJJ
C150X030Y1J	Complex	C150X030Y1C	LS8EQ
UILJ4	Complex	UILS8BW	LS8EQ