

EOL of Select 25nm LPDDR3 6Gb V9AM packages

PCN: 32047 Published: 2016-09-02

Type:	End of Life  Micron is announcing the EOL of certain 25nm LPDDR3 6Gb V9AM packages  Better Align With Industry Standard, Change in Market Demand  Select V9AM Marketing part numbers with very low or no demand		
Description:			
Reason:			
Product Affected:			
Affected Micron Part Number	er	Recommended Replacement	<b>Customer Part Number</b>
Component			
EDF620AAABH-GD-F-D			
EDFP112A3PB-GD-F-D			
EDFP112A3PB-GD-F-R			
EDFP112A3PB-GDTJ-F-D			
EDFP112A3PB-GDTJ-F-R			
EDFP112A3PB-JD-F-D			
EDFP112A3PB-JD-F-R			
EDFP112A3PB-JDTJ-F-D			
EDFP112A3PB-JDTJ-F-R			
EDFP112A3PD-GD-F-D			
EDFP112A3PD-GD-F-R			
EDFP112A3PF-GD-F-D			
EDFP112A3PF-GD-F-R			
EDFP112A3PF-GDTJ-F-D			
EDFP112A3PF-GDTJ-F-R			
EDFP112A3PF-JD-F-D			
EDFP112A3PF-JD-F-R			
EDFP112A3PF-JDTJ-F-D			
EDFP112A3PF-JDTJ-F-R			
EDFP164A3PB-GD-F-D			
EDFP164A3PB-GD-F-R			
EDFP164A3PD-GD-F-D			
EDFP164A3PD-GD-F-R			
EDFP164A3PD-MD-F-D			
EDFP164A3PD-MD-F-R			
		*Materials that have been ordered are in	n <b>bold</b> .
Method of Identification:	Marketing F	Part Number	
Micron Sites Affected:	All Sites		
Qualification Plan:	There is no specific replacement for V9AM products		
Last Purchase Date*:	2017-03-02		

<sup>\*</sup>Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

## **Micron Confidential and Proprietary Information**

2017-09-02

## Thank you

**Last Shipment Date:** 

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.