

Doc. No. : PDN220402
Date : Apr 15, 2022

To : Dear Valued Customers

Product Discontinuance Notice

Subject : AS9013-x-HF Series products discontinue.									
Parts Affected :									
<table border="1"><thead><tr><th>Part No.</th><th>Package Type</th></tr></thead><tbody><tr><td>AS9013-L-HF</td><td>SOT-23</td></tr><tr><td>AS9013-J-HF</td><td>SOT-23</td></tr><tr><td>AS9013-H-HF</td><td>SOT-23</td></tr></tbody></table>		Part No.	Package Type	AS9013-L-HF	SOT-23	AS9013-J-HF	SOT-23	AS9013-H-HF	SOT-23
Part No.	Package Type								
AS9013-L-HF	SOT-23								
AS9013-J-HF	SOT-23								
AS9013-H-HF	SOT-23								
Reason for Discontinuance :									
Due to low demand, the part listed below will be discontinued.									
Alternative Products :									
Please contact sales person or manufacturer's representative.									
Last time buy : Dec 30, 2026 Effective Date : Mar 30, 2027									
R&D Dept. Signature :	QA Dept. Signature :								
									