




Product Change Notification (PCN)

PCN Number	508745	Date Issued	April 30, 2020
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	No change to parts/components FFF		
Internal Molex Qualification Date	April 10, 2020		
Sample Availability Date (Changed Part)	April 10, 2020		
Planned Implementation Date	May 07, 2020		
Method of Identifying Change	No special marking on the product or packaging		

RELEASED

Before Change

Changing Point



After Change

Overview

- Reason for change
 - Soldering iron method in both Product Specifications will be changed/added due to optimize Manual Soldering Specification
- Product Impact
 - No impact to Fit, Form or Function
- Part Number Impact
 - 55445-1029, 53460-0639, 53984-0681
- How the change implement
 - Use as is
- Qualification Reports and samples available upon request after the date shown above



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:508745**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

PCN #	Molex Part #
508745	534600639
508745	539840681
508745	554451029