

Revision 1.0.0 ADV Issue Date: 04/05/2019

CUSTOMER ADVISORY ADV1902

Stratix®10 FPGA Firmware Updates

Change Description

Intel Programmable Solutions Group ("Intel PSG," formerly Altera) is notifying customers of Stratix 10 firmware updates.

It was recently determined that the Stratix 10 firmware is not applying optimized onchip voltage regulator trim settings and therefore may cause a slight timing model mis-correlation. Optimized settings, available through a firmware update, will restore the correlation. It is required that customers apply this updated firmware to future Stratix 10 devices.

This firmware update:

- does not require recompilation or change design timing;
- has no impact on design functionality or performance;
- has no impact on power specifications as power models in EPE are already based on optimized regulator trim settings;
- has no impact to form, fit, or function.

Recommended Actions

Please refer to the following table to determine the appropriate actions for the firmware update:

Table 1

Customer Design Status	Customer Deployment Timeframe		Recommended Actions	
Intel Stratix 10 designs in production	For devices deployed by customers before end of June 2019.		Bitstream regeneration is optional. No adverse impact from regenerating the bitstream if you want a single POF. Optionally download the patch to regenerate the bitstream.	

Intel Corporation Page 1 of 3 04/05/2019 ADV1902

-			
	For devices	•	Bitstream regeneration is required.
	deployed by	•	Firmware update applies optimized on-chip
	customers after		voltage regulator trim settings that improves
	end of June 2019.		timing correlation, to accommodate future
			natural manufacturing variations.
		•	Download the patch to regenerate the
			bitstream or migrate to Intel Quartus Prime
			Pro Edition software version 19.1 (includes
			updated firmware) by end of June 2019.
Designs not in	All devices	•	Download the patch to regenerate the
production			bitstream or migrate to Intel Quartus Prime
			Pro Edition software version 19.1 (includes
			updated firmware).

For details on the patches, steps to apply the patch, and steps to regenerate the bitstream, refer to the following knowledge database link:

https://www.intel.com/content/altera-www/global/en_us/index/support/support-resources/knowledge-base/component/2019/is-there-an-update-to-intel--stratix-10-firmware-.html

For any additional questions or support please contact your local Field Applications Engineer (FAE) or submit an IPS ticket at the My Intel support page.

Products Affected

All Intel Stratix 10 FPGA devices.

The list of affected OPNs can be downloaded in Excel form:

https://www.intel.com/content/dam/www/programmable/us/en/pdfs/literature/pcn/adv1902-opn-list.xlsx

Reason for Change

Due to an inconsistency between the Intel Stratix 10 firmware and internal manufacturing testing, firmware was not applying optimized on-chip voltage regulator trim settings and therefore may cause a slight timing model mis-correlation. Optimized settings are applied using updated firmware and will restore the correlation.

Intel Corporation Page 2 of 3 04/05/2019 ADV1902

Change Implementation

Table 2

Milestone	Date of Availability
Patches with updated Intel Stratix 10 firmware in	
Intel Quartus Prime Pro Edition Software version	Now
18.0.1, 18.1, 18.1.1, 18.1.2	
Patches with updated Intel Stratix 10 firmware in	
Intel Quartus Prime Pro Edition Programmer	Now
version 18.0.1, 18.1, 18.1.1, 18.1.2	

The updated Intel Stratix 10 firmware will be available in the Intel Quartus Prime Pro Software version 19.1 and all subsequent versions.

Contact

For more information, please contact your local Field Applications Engineer (FAE) or submit a IPS ticket at the <u>My Intel</u> support page.

Customer Notifications Subscription

Customers that subscribe to Intel PSG's customer notification mailing list can receive the Customer Advisory automatically via email.

If you would like to receive customer notifications by email, please subscribe to our customer notification mailing list at:

https://www.intel.com/content/www/us/en/programmable/my-intel/malemailsub/technical-updates.html

Revision History

Date	Rev	Description
04/05/2019	1.0.0	Initial Release

©2019 Intel Corporation. All rights reserved. Intel, the Intel logo, Altera, Arria, Cyclone, Enpirion, MAX, Nios, Quartus and Stratix words and logos are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries. Intel warrants performance of its FPGA and semiconductor products to current specifications in accordance with Intel's standard warranty, but reserves the right to make changes to any products and services at any time without notice. Intel assumes no responsibility or liability arising out of the application or use of any information, product, or service described herein except as expressly agreed to in writing by Intel. Intel customers are advised to obtain the latest version of device specifications before relying on any published information and before placing orders for products or services. Other names and brands may be claimed as the property of others.

Intel Corporation Page 3 of 3 04/05/2019 ADV1902