

TE Connectivity

Product Change Notification: E-19-006178 PCN Date: 16-MAY-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
CHANGES TO FLIP LOCATOR ON 91576

Description of Changes

Hello, You are receiving this Product Change Notice in regard to Certicrimp II tool 91576. No action is required at this time. The tool has had a component of the flip locator changed to increase ease of use. Tools in the field are unaffected by this change.

Reason for Changes:					
Product Improvement.					
Estimated Dates:					
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):				
	10-JUN-2019				
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):				
	No Mixed Shipments				

Part Number(s) being Modified:

Part Number	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
91576-1	NO						

Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>91576-1</u>	NO						

Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>91576-1</u>	NO						