

Micron Technology, Inc. 8000 S. Federal Way PO Box 6 Boise, ID United States

V89C FBGA Assembly Site Transfer from ChipMOS (TW) to PTI-Xian (CN) - Automotive / Product Longevity Program

PCN: 32351

Published: 2017-06-09

Revision History:

Revision 1, 2017-12-22: This document supersedes the original PCN #32351, dated 2017-06-09. The Last Shipment Date has been changed from 2019-05-31 to 2018-08-31.

Туре:	Manufacturing Site – Change or Addition		
Description:	/89C FBGA SDP, currently assembled at ChipMOS TW, is being transferred to PTI-Xian. Last Time Buy and Last Time Ship Dates are included below for material assembled at ChipMOS.		
	Site Locations:		
	 ChipMOS Technologies, Inc. No 5 Nan-KO Rd 7 Science Based Industrial Park, Taiwan, TW 		
	 PTI-Xian: Powertech Semiconductor Xian Co Ltd, 28 Xinxi Avenue, 710119 Xian, China 		
Reason:	Manufacturing Efficiency, Supply Flexibility/Security		
Product Affected:	V89C FBGA SDP x8/x16		
Affected Micron Par Number	t Recommended Replacement Customer Part Number		
<u>Component</u>			
MT41K128M16JT-1	25 MT41K128M16JT-125		

AAT:K			AAT:K-ND	
MT41K128M16JT-12	5 AIT:K			
MT41K128M16JT-12 AUT:K	5			
MT41K128M16JT-12 AIT:K	5 M			
MT41K128M16JT-12	5 V:K			
MT41K128M16JT-12 XIT:K	25		MT41K128M16JT-125 XIT:K-ND	
MT41K256M8DA-10	7 AIT:K			
MT41K256M8DA-125 AAT:K				
MT41K256M8DA-125 AIT:K				
MT41K256M8DA-125 AUT:K				
*Materials that have been ordered are in bold .				
Method of Identification:	Country of origin on the component mark			
Micron Sites Affected:	Subcontractor			
Qualification Plan:	Will be qualified according to Micron's standard qualification processes			
Sample Available:	2017-07-04			
Qual Data Available:	2017-07-04			

Available:	2017-07-04
Product Ship Date:	2017-09-07
Last Purchase Date*:	2018-05-31
Last Shipment Date:	2018-08-31

*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.