



Product End Of Life Notification		Date November 7, 2016
Product	Consolidation of SKUs: PortServer TS Hcc 1 port & PortServer TS Haz Notice # 161107-01	

Reason for Change :

<input type="checkbox"/> Technical Requirement	<input type="checkbox"/> Product Transition
<input type="checkbox"/> Customer Requirement	<input checked="" type="checkbox"/> Product Discontinuation
<input type="checkbox"/> Quality Improvement	<input type="checkbox"/> Product Enhancement
<input type="checkbox"/> Change of Production Location	<input type="checkbox"/> Other (Brand Change)

Description of change	<p>PortServer TS MEI Hcc 1 port and PortServer Ts MEI Haz 4 port products are being discontinued.</p> <p>This is an ongoing effort to streamline and consolidate our product offerings to focus on consistent product availability while maintaining our high quality.</p> <p>All LTB purchase orders are NCNR (non-cancellable/non-returnable).</p> <p>Standard warranty policy will apply to all LTB purchases.</p>
------------------------------	---

Part Numbers	70002038 PortServer TS 1 Hcc MEI 70002320 PortServer TS 4 Haz MEI
---------------------	--

Timing of Change	Last time buy orders must be received by: February 10, 2017 Last time ship date for all confirmed orders: February 24, 2017
Replacement Product	Below are <u>suggested replacements</u> to the right of the arrow: 70002038 → 70002039 PortServer TS 2 Hcc MEI Difference is the numbers of serial ports. 1 port vs. 2 ports. 70002320 → 70002040 PortServer TS 4 Hcc MEI Difference is name of product on the overlay and C1D2 certs were on 70002320. 70002040 has NEMA TS 2 certification, but not C1D2.

Last Time Buy Parts	Yes
Quality Issues	None
Authorization	Kim Knutsen, Sr. Product Manager, Digi International