



## Product Change Notice: ETQ-P4M6R8KVC Series PCC-MC

PCN.PG47.08.11.2017

updated (for Digi-Key) 08/28/17

<b>About This Notice:</b>	The internal winding shape changes for yield improvement, with no change in electrical characteristics, quality, or reliability robustness.
<b>Effective Date:</b>	Factory shipments from September 1, 2018
<b>Change Details:</b>	Internal coil shape change
<b>Affected Parts:</b>	ETQ-P4M6R8KVC
<b>Datasheet(s):</b>	<a href="https://industrial.panasonic.com/cdbs/www-data/pdf/AGL0000/AGL0000C63.pdf">https://industrial.panasonic.com/cdbs/www-data/pdf/AGL0000/AGL0000C63.pdf</a>
<b>Notes:</b>	Detailed spec included. 500pcs shipped to Digi-Key, with the current coil winding shape, in May 2017. The Lot No. was 7424S21 and the Serial No. was L7424S21URT. The new coil winding shape will be used in parts after this Lot no.