



Product Termination Notification



Product Group: Opto Modules & Visibles 05-MAR-2018 / PTN OMV-1013-2018 Rev. 0

TITLE: Product Discontinuation of no Running Visible Parts

DESCRIPTION OF CHANGE: Product discontinuation. Phase out of products released before 2016 and with no sales for more than 2 years.

CLASSIFICATION OF CHANGE: Product Obsolescence

REASON FOR CHANGE: Product discontinuation due to no Business last 2 years

PRODUCT CATEGORY: LEDs

PART NUMBERS / SERIES / FAMILIES AFFECTED:

according attached part number list

VISHAY BRAND(s): VISHAY SEMICONDUCTORS

TIME SCHEDULE:

Annotations about time schedule:

Last Time Buy Date: 21-FEB-2018

Last Time Shipment Date: 21-FEB-2018

SAMPLES AVAILABLE BEGINNING:

We need samples of replacement parts for evaluation: Yes No

If Yes return this form to contact information below.

This PCN is considered approved, without further notification, unless we receive specific customer concerns before: 23-FEB-2018 or as specified by contract.

ISSUED BY:

PM: Franz Rettenmeier, Product Marketing Visibles

Phone: (+49) 7131 67-2276

Email: franz.retteneier@vishay.com

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

VISHAY Intertechnology Asia Pte. Ltd.
Regional Marketing Asia/Japan
 25 Tampines Street 92
 Keppel Building # 02-00
 Singapore 528877
 Phone: +65-6788-6668
 Fax: +65-6788-3383

VISHAY Intertechnologies, Inc.
Regional Marketing The Americas - Opto
 2201 Laurelwood Road
 M/S 55
 Santa Clara, CA 95014
 USA
 Phone: +1-408-567-8317
 Fax: +1-408-567-8371

VISHAY Semiconductor GmbH
Regional Marketing Europe Opto
 Theresienstr. 2
 D-74025 Heilbronn
 Germany
 Phone: +49-7131-672666
 Fax: +49-7131-673144



Product Termination Notification



Product Group: Opto Modules & Visibles

05-MAR-2018 / PTN OMV-1013-2018 Rev. 0

Attached Part Number List:

VLSL12A03-3Q3T-50A;;TLLG5400-AS12 T5910VA-SF-F;;TLUG2400-ASZ T6110VA-SF-F;;TLUG2400-MS12Z T6310VA-SF-F;;TLUG2400-MS21Z VLRE31R1S1-GS08;;TLUG2401-AS12 VLRE31R1S1-GS18;;TLUG2401-AS12Z VLRE31R1S2-GS18;;TLUO2401-AS12 VLRE31R2S2-GS08;;TLUR2400-AS12 VLRE31R2S2-GS18;;TLUR2401-AS12 VLRK31Q1R2-GS18;;TLUY2400-AS12 VLRK31Q2R1-GS08;;TLUY2401-AS12Z VLRK31Q2R1-GS18;;VLME31Q2T1-35-GS08 VLRK31R1R2-GS08;;VLME31Q2T1-35-GS18 VLRK31R1R2-GS18;;VLMF31R1S2-35-GS08 VLRK31R1S2-GS18;;VLMF31R1S2-35-GS18 TDCY1050M;;VLMF31R1S2-GS08 TDCY1060M;;VLMF31R1S2-GS18 TDSG3151;;VLMK31P2S1-GS08 TDSO3153;;VLMK31P2S1-GS18 TDSO1160-K;;VLMK33R2T2-2-GS08 VLME23N1P1-35-GS08;;VLMO31J1K2-35-GS08 VLME23Q2S1-GS08;;VLMP3107-GS08 VLMF23Q2T1-GS08;;VLMP3107-GS18 VLMK23Q2S1-GS08;;VLMPG30E1F2-GS08 VLMO2000-GS08;;VLMPG30E1F2-GS18 VLMO20K1L2-34-GS08;;VLMPG30E1G2-GS08 VLMO21H2L1-GS08;;VLMPG30E1G2-GS18 VLMS20J2K2-GS08;;VLMPG30F1G2-GS08 VLMY21H2K1-GS08;;VLMPG30F1G2-GS18 VLMY21H2L1-GS08;;VLMR3342V1AA62A-08 VLMY21J2L1-GS08;;VLMY33T2U2-46-GS08 TLHE4200;;VLMYG30G2J1-GS08 TLHG5400-BT12;;VLMYG30G2J1-GS18 TLHK5100-AS12Z;;VLMYG30G2K1-GS08 TLHO2400;;VLMYG30G2K1-GS18 TLHR4400-AS21Z;; TLHY4200-AS12Z;; TLHY6200-CS12;; TLLG4401-AS12Z;;