

TE Connectivity

Product Change Notification: P-19-017766 PCN Date: 14-AUG-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
AMPLIVAR Splices Strip

Description of Changes

For following PNs are currently single manufacturing source at TE Lickdale, USA. These parts will be Dual manufacturing source at TE Lickdale USA and TE Qingdao China in the future.

Reason for Changes:

Dear Customer, as a result of our continuous strive for improving our supply chain, we hereby inform you about the changing of manufacturing location to improve capacity and lead time. The new manufacturing location is changed by following a strict procedure, which guarantees quality, ability to supply and form fit function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):			
	15-SEP-2019			
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):			
	No Mixed Shipments			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
62000-2	NO						
<u>62157-1</u>	NO						
<u>62157-2</u>	NO			"4-18220-0010"			
<u>62305-2</u>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
62000-2	NO						
62157-1	NO						
<u>62157-2</u>	NO			"4-18220-0010"			
<u>62305-2</u>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
62000-2	NO						
<u>62157-1</u>	NO						
<u>62157-2</u>	NO			"4-18220-0010"			
<u>62305-2</u>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>62000-2</u>	NO						
62157-1	NO						
62157-2	NO			"4-18220-0010"			
<u>62305-2</u>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
62000-2	NO	Diawing	Italiibei	Humber(3)	Number	rumber(3)	Difference
<u>62157-1</u>	NO						
<u>62157-2</u>	NO			"4-18220-0010"			
62305-2	NO						

Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of			
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference			
<u>62000-2</u>	NO									
<u>62157-1</u>	NO									
62157-2	NO			"4-18220-0010"						
62305-2	NO									