

IloT Product Change Notice

The change(s) will be applied on the affected products, if you need more information or special support, please contact PM: **Zoe Tsai** (TEL: +886-2-2792-7818, ext: **1717**; e-Mail: zoe.tsai@advantech.com.tw)

1. Reason for the Change: **update cable for non-parallel port PN**

2. Affected Product: PCA-6028/6029,

PCE-7132/5132/5032/7131/5131/5031/7129/5129/5029/7128/5128/4129/3029/4128/3028, PCI-7032

3. Impact on Application:

Item	Impact
Ex: Impact on Customer Mechanical Design	No
Ex: Physical Outlook Change	Yes

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
PCA-6028G2-00A2E	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCA-6028VG-00A2E	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCA-6029G2-00A2	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-5029G2-00A3E	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-5029VG-00A2E	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-5031G2-00A2	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-5032G2-00A2	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-5128G2-00A2E	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-5129G2-00A2E	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-5131G2-00A2	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-5132G2-00A2	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-7128G2-00A2E	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-7129G2-00A2E	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-7131G2-00A2	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-7132G2-00A2	1701260305	1701090401	COM/Parallel port cable	Yes	To remove parallel port cable
PCE-3028G2-00A2E	1700002223-11	-	Parallel port cable	Yes	To remove parallel port cable
PCE-3029G2-00B2E	1700002223-11	-	Parallel port cable	Yes	To remove parallel port cable
PCE-4128G2-00A2E	1700002223-11	-	Parallel port cable	Yes	To remove parallel port cable
PCE-4129G2-00B2E	1700002223-11	-	Parallel port cable	Yes	To remove parallel port cable
PCI-7032G2-00A2E	1700002223-11	-	Parallel port cable	Yes	To remove parallel port cable
PCI-7032VG-00A2E	1700002223-11	-	Parallel port cable	Yes	To remove parallel port cable



5. Implementation & Schedule of the Change(s):


Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
PCA-6028G2-00A2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCA-6028VG-00A2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCA-6029G2-00A2	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-5029G2-00A3E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-5029VG-00A2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-5031G2-00A2	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-5032G2-00A2	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-5128G2-00A2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-5129G2-00A2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-5131G2-00A2	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-5132G2-00A2	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable

PCE-7120G2-00A2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-7129G2-00A2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-7131G2-00A2	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-7132G2-00A2	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-3028G2-00A2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-3029G2-00B2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-4128G2-00A2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCE-4129G2-00B2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCI-7032G2-00A2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable
PCI-7032VG-00A2E	ECOM-175942	Sep., 2021	Cut in 4	To remove parallel port cable

*Note: Cut-in progress depends on factory production schedule, what listed in this table is ESTIMATED time-frame.

6. Image Comparison

Full-sized SBC	1701260305	1701090401
Appearance view		
Description	COM + Parallel Port cable	Single COM cable

Half-sized SBC	1700002223-11	-
Appearance view		-
Description	1-port Parallel port cable	-

Contact Windows

PM	Zoe Tsai / zoe.tsai@advantech.com.tw / 511-1717
AE	AE.ISG.ACL@advantech.com