

Product Change Notification (PCN)

510966 Date Issued January 17, 2022 PCN Number

Reason for Change Capacity change or tool replacement

Change Type Description This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product.

There will be no changes in the fit, form or function from the

additional tooling when compared to the current tooling.

Reason for Short Notice **New Capacity**

Product will be fully qualified before it is shipped. Qualification Assessment of Change

reports will be available after below listed date

Internal Molex Qualification Date November 19, 2021

> Sample Availability Date November 19, 2021 (Changed Part)

Planned Implementation Date February 16, 2022

Method of Identifying Change Product made after planned implementation date can contain the change

Before Change

5557 Series



After Change

Overview

- To ensure business continuity, another set of tooling is being added
 - New tooling will be an exact replica of current tooling
 - Tooling being added to keep up with current and future demand
- There is NO impact to Fit, Form or Function
- Samples available upon request after date shown above
- Part Numbers Impacted
 - See attached list



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:510966" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

PCN #	Molex Part #	
510966	39012100	
510966	39012105	
510966	39039102	
510966	469921010	
510966	2153251103	
510966	2451351005	
510966	2451351010	

Affected Parts:

39-01-2100
39-01-2105
215325-1101
215325-1102
215325-1103
215325-2101
215325-2102
215325-2103
215325-2103 215326-1101
215326-1101
215326-1101 215326-1102
215326-1101 215326-1102 215326-1103