

Issue Date: October 28th, 2020

Dear Valued Customer,

This notice is to inform you of our efforts in re-sourcing the raw material used in a component of finished goods that you have purchased from Littelfuse in the past.

Description of the Change:

- We will be changing the resin used on the cover featured in the following finished goods: 04981038HXFC, 04981038HXFC-A, 04982001ZXFC, and 04982002ZXFC.

Reason for The Change:

- The current resin supplier has informed us of the sudden cessation of production of the resin we have used in this cover since its launch.
- Littelfuse will be moving to a material and resin provider currently employed in other similar products we currently produce.

Effective Date of the Change:

- This will occur as a running change; production utilizing the new resin is expected to begin no later than Thursday, November 12th. Shipments of such modified products will begin shortly thereafter.

What You Need to Do:

- No change is required on your part. This transition in material is not expected to result in a change in component or finished good fit, form, or function.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,



Zachary Naughton
Global Product Manager
Littelfuse Commercial Vehicle Products