

Issue Date: June 22th, 2020

Dear Valued Customer,

This notice is to inform you of the immediate delay in shipment of a product you have purchased from Littelfuse.

Description of the Change:

- We will no longer supply the current revision of finished good 00800000; there will be an approximate 10 week delay before we can supply a replacement finished good.

Reason for The Change:

- Due to a partner vendor's inability to support production of a component required for this finished good, Littelfuse will not be able to support production of this finished good at this time.
- Littelfuse has begun the immediate re-design and validation of a replacement component (and subsequently replacement finished good) that will perform at or exceeding previous performance.

Effective Date of the Change:

- This stop shipment is effective immediately, including current open orders.
- The design update will be completed and launched by the end of Q3 2020.

What You Need to Do:

- Due to the sudden nature of this change, we will not be able to support additional purchase orders with the current components on-hand. Open orders on this part number will require delay in projected fulfillment date.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,



Zachary Naughton
Global Product Manager
Littelfuse Commercial Vehicle Products