

PRODUCT CHANGE NOTIFICATION

Product Category Computer Printables 20221202-1

Product Group ID AND SAFETY

ISSUE DATE: 2-Dec-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Effective January 1, 2023, the PES400 Embossing System repair service location will move from Panduit Georgia to Panduit Lockport. The Panduit Lockport group will provide repair service for PES400 units going forward. Any questions about this transfer can be directed to Chris McConnell, Senior Product Manager, or to the Panduit ID Product Management Group.

The Identification Products Group at Panduit Georgia will continue to provide Technical Support, Product Management, and Engineering coverage for the PES400. Please contact the Identification Products Technical Support group at 1-866-871-4571, or GA-TECHSUPPORT@panduit.com, for any troubleshooting or assistance prior to a PES400 repair.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*			